

25X1A

Approved For Release 2003/09/30 : CIA-RDP75B00326R000200020022-8		GROUP 1 EXCLUDED FROM AUTOMATIC DECLASSIFICATION		1	6
ADVANCE COPY <input type="checkbox"/> ISSUED <input type="checkbox"/> SLOTTED <input type="checkbox"/>		REPRODUCTION OF THIS COPY PROHIBITED		2	7
BY: _____ AT: _____ Z		INDEX: <input type="checkbox"/> YES <input type="checkbox"/> NO		3	8
DISSEM BY: _____ PER _____		CLASSIFY TO FILE NO. _____		4	9
ACTION: <u>C/SOD 3</u> <input checked="" type="checkbox"/> RID COPY		X-REF TO FILE NO. _____		5	10
FILE NO. _____		FILE RID <input type="checkbox"/> RET. TO _____			
INFO: _____		BRANCH <input type="checkbox"/>		DESTROY <input type="checkbox"/> SIG. _____	
VR. <u>C/FES, C/SAUA, DDS2 C/DDS/HB3</u>					

S E C R E T 191340Z JUN 68 CITE [REDACTED]

C/PPB ADDP, DD25X1A

25X1A IMMEDIATE [REDACTED]

AS100, C/OPSER,

25X1A RYBAT [REDACTED]

D/MS2,

REF: [REDACTED]

19 JUN 68 IN 34200

25X1A [REDACTED]

25X1A SUBJECT: [REDACTED] STROKE REF BEING PASSED TO ADDEES.

25X1A GIVES MEDICAL OPINION OF [REDACTED] CASE AND OXYGEN SYSTEM.

1. SEVERAL AIR AMERICA PILOTS REPORTED TO [REDACTED]

25X1A

25X1A [REDACTED] 18 JUNE 68 A SIMILAR STROKE IN THE RED DOOR BAR ACROSS
FROM AIR AMERICA, BANGKOK PRIOR TO THE STROKE 17 JUNE 1968.25X1A 2. [REDACTED] DID NOT REPORT THIS ATTACK TO THE AIR AMERICA
FLIGHT SURGEON VIENTIANE.

25X1A 3. AS INDICATED IN [REDACTED] SEVERAL PILOTS ATTEMPTED
PRESSURE USAF FLIGHT SURGEON KNP TO DECLARE VTB OXYGEN SYSTEM
INADEQUATE. THERE WAS MUCH INITIAL EMOTION REFERENCE LAST
TWO LINES IN A/MFD SZ SVKT 162345. [REDACTED] ADMONISHED BOTH FOR
SPECULATING RATHER THAN REPORTING FACTS. [REDACTED] REPORTS
THE [REDACTED] PILOT SITUATION HAS STABELIZED.

25X1A

25X1A

25X1A

25X1A 4. SEVERAL PILOT OPINIONS PREVIOUSLY EXPRESSED SURFACED
WITH [REDACTED] AT FIRST APPARENT PHYSICAL CONDITION BEING RELATED
TO OXYGEN DEFICIENT AND EXPOSURE TO ALTITUDE:

A. RUGGED MONOTONOUS FLYING INADEQUATELY COMPENSATED
REDUCED PROJECT PAY.

SECRET

PAGE TWO [REDACTED] S E C R E T

B. INCREASING HAZARDS IN THE FLIGHT PATTERN.

C. [REDACTED] WHEELS UP LANDING AND GROUNDING

DIRECTLY RELATED TO LONG FLIGHT AT ALTITUDE WITH
INADEQUATE OXYGEN EQUIPMENT AND PAINFUL EARPHONES,
AFTER PERFORMING OUTSTANDINGLY FROM 16 MARCH 1967.

D. CAUSAL RELATIONSHIP BETWEEN [REDACTED] ILLNESS -
NOW ON LEAVE - REPORTEDLY ASCRIBED TO [REDACTED]
PERSONAL DOCTOR.

E. DESIRE TO GET IN OTHER FLYING PROGRAMS WHERE
THEY CAN FULFILL THEIR OBJECTIVE IN FLYING FOR AIR
AMERICA IN LAOS - MORE GROSS PAY.

5. ACCOUNT ABOVE OPINIONS, ESPECIALLY THE IMPUTED
RELATIONSHIP OF ALTITUDE FLYING COUPLED WITH ALLEGED DEFICIENT
AND ANTIQUATED OXYGEN EQUIPMENT CAUSING INDUSTRIAL TYPE ILLNESS.
SUGGEST DIRECTOR OF TRAINING [REDACTED] PHYSIOLOGICAL
INSTRUCTOR VISIT [REDACTED] TO EXAMINE OXYGEN EQUIPMENT, AGAIN
HOLD DISCUSSIONS ON PHYSIOLOGICAL PROBLEMS AND ATTEMPT TO PROCURE
PERSONAL OXYGEN MASKS.

S E C R E T